

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD,
17-FDWA,
7-

Fort Washington, Main Gate
(Sally Port)
Fort Washington Road
Fort Washington Forest vicinity
Prince George's County
Maryland

HABS No. MD-307-A

Unknown, Photographer, Fall 1948

MD-307-A-1 SOUTH ELEVATION

Abbie Rowe, Photographer, June 7, 1957

MD-307-A-2 DETAILED VIEW OF SOUTH ELEVATION SHOWING
WINDOWS, WINDOW SURROUNDS WITH SEMI-CIRCULAR
ARCHES SPRINGING FROM FLAT HEADERS, AND GATE
COLUMN

Abbie Rowe, Photographer, November 6, 1957

MD-307-A-3 DETAILED VIEW (SOUTH) OF DRAWBRIDGE GATE

MD-307-A-4 DETAILED VIEW OF DRAWBRIDGE MACHINE

Abbie Rowe, Photographer, April 25, 1958

MD-307-A-5 DETAILED VIEW (NORTH) OF INTERIOR GATE SHOWING
CROSS-BAR

Unknown, Photographer, June 21, 1957

MD-307-A-6 DETAILED VIEW OF HERRING BONE BRICK PAVING PATTERN

Unknown, Photographer, August 9, 1941

MD-307-A-7 PERSPECTIVE VIEW (NORTH) SHOWING OUTER WALL OF
MOAT AND LOWERED DRAWBRIDGE

MD-307-A-8 PERSPECTIVE VIEW OF DEMILUNE MOAT

HISTORIC AMERICAN BUILDINGS SURVEY
Index to photographs
Fort Washington, Main Gate
(Sally Port)

HABS No. MD-307-A
(Page 2)

Abbie Rowe, Photographer, April 16, 1958

MD-307-A-9 PERSPECTIVE VIEW OF EAST SIDE AT TERREPLEIN LEVEL

Abbie Rowe, Photographer, January 20, 1958

MD-307-A-10 PERSPECTIVE VIEW OF NORTH (REAR) AND WEST SIDE OF
SECOND FLOOR, WEST ROOM SHOWING RELATIONSHIP TO
NORTH TERREPLEIN OF NORTHWEST DEMI-BASTION AND
STAIRS LEADING TO GUN MOUNT ABOVE MAIN GATE

Abbie Rowe, Photographer, December 19, 1957

MD-307-A-11 DETAILED VIEW OF NORTHWEST CORNER AT TERREPLEIN
LEVEL SHOWING STONE QUOINS, ENTABLATURE AND CORNICE

Unknown, Photographer, Fall 1948

MD-307-A-12 PERSPECTIVE VIEW (NORTHEAST) SHOWING GUN MOUNT
ABOVE MAIN GATE

Abbie Rowe, Photographer, April 16, 1958

MD-307-A-13 DETAILED VIEW OF FIRST FLOOR, EAST ROOM FIREPLACE
(EAST WALL) AND WINDOWS BEFORE RESTORATION

Abbie Rowe, Photograph, October 30, 1958

MD-307-A-14 DETAILED ELEVATION OF FIRST FLOOR, EAST ROOM
FIREPLACE OPENING AND WINDOW ON EAST WALL DURING
RESTORATION

Abbie Rowe, Photographer, November 28, 1958

MD-307-A-15 INTERIOR VIEW OF FIRST AND SECOND FLOOR (FLOOR
REMOVED) EAST ROOMS DURING RESTORATION

MD-307-A-16 DETAILED VIEW OF FIRST AND SECOND FLOOR (FLOOR
REMOVED) EAST ROOMS SHOWING FIREPLACE AND WINDOWS
ON EAST WALL

HISTORIC AMERICAN BUILDINGS SURVEY
Index to photographs
Fort Washington, Main Gate
(Sally Port)

HABS No. MD-307-A
(Page 3)

Abbie Rowe, Photographer, April 16, 1958

MD-307-A-17 DETAILED VIEW OF FIRST FLOOR, WEST ROOM FIREPLACE
(WEST WALL) AND DOOR BEFORE RESTORATION

Abbie Rowe, Photographer, October 17, 1958

MD-307-A-18 PERSPECTIVE VIEW INTO SECOND FLOOR, WEST ROOM (ROOF
REMOVED) DURING RESTORATION

Abbie Rowe, Photographer, November 28, 1958

MD-307-A-19 INTERIOR VIEW OF FIRST AND SECOND FLOOR (FLOOR
REMOVED) WEST ROOMS SHOWING DOORS IN NORTH WALL

Abbie Rowe, Photographer, November 21, 1958

MD-307-A-20 DETAILED ELEVATION OF DOOR, SECOND FLOOR, WEST
ROOM, NORTH WALL